



## State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

NGC74

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

October 27, 2000

TO:	Internal File			
THRU:	Daron R. Haddock, Permit Supervisor			
FROM:	David W. Darby, Senior Reclamation Specialist			
RE:	1999, Fourth Quarter Water Monitoring, Genv Canyon Mine, ACT/015/032	val Resources	s, Inc., Crand	<u>lall</u>
	a submitted for all of the MRP required sites? ify sites not monitored and reason why, if known	YES [7	X] NO	[ ]
See T five-y the M	date does the MRP require a five-year resample chnical Directive 004 for baseline resampling rear baseline resubmittal when responding to que IRP does not have such a requirement.  mpling due date 5/13/2003	requirements.	Consider th	he
3. Were all required parameters reported for each site?  Comments, including identity of monitoring site:		YES[X] NO[]		
	egularities found in the data? ments, including identity of monitoring site:	YES [	X] NO	[]
5. Were DM	IR forms submitted for all required sites?			
Identii	fy sites and months not monitored:	2 <sup>nd</sup> month,	YES [X] YES [X] YES [X]	
1	y		[ ]	

ACT/015/032-WQ99-3 October 27, 2000 Page 2

6. Were all required DMR parameters reported?

YES[X] NO[]

Comments, including identity of monitoring site:

7. Were irregularities found in the DMR data?

YES[X] NO[]

Comments, including identity of monitoring site:

Site SP1-19 reported a specific conductance of 4.03, is most likely 404, because lab reported a spec. cond. of 570 micromhos/cm.

8. Based on your review, what further actions, if any, do you recommend?

More careful recording by the operator and lab.

sm

O:\015032.CRA\Water Quality\WQ\_99-4.wpd